Columbus Airport Maintenance Department Hangar Work Orders September 25th, - October 15, 2019

- 1-B: Overhead light is inoperable
- 1-B: Door catch plate and lock pin is missing
- 1-B: Bolts missing on door tracks
- 1-B: Doors are hard to open and don't operate smoothly
- 1-C: Debris and grass on Exterior door tracks
- 1-C: Door catch plate is too short.
- 1-C: Gutter is rusted above the door
- 1-D: Ants present in the back corner
- 1-E: Door skin and frame are bent on the right-hand side
- 1-E: Wood paneling is warped from water damage and needs to be replaced
- 2-A: Debris and grass on Exterior door tracks
- 3-A: Surface rust on walls; bolts missing on door tracks
- 3-B: Overhead light is inoperable
- 3-C: Doors are hard to open and don't open smoothly
- 3-C: Bird nest in Left-Hand corner
- 3-D: Doors are hard to open
- 3-E: Bird evidence is present; close gaps in the doors to prevent re-entry