

Hangar Work Orders

12/01/2019 – 12/15/2019

#85 Hangar 4 C gutter is sagging. Repair/ Readjust to straighten gutter so that water flows to the downspout.

Work Complete

#84 Hangar 2-D (Facing gate 6) RH door sagging. Nut is missing from I-bolt on the top. Sheet metal is separated on the exterior. Need to fabricate/re-attach with rivets.

Work Complete

#83 Hangar 11 Bay 5: Bottom door roller 3rd door on the left, interior roller. Roller is wobbly, unsteady. needs to be adjusted.

Work Complete

#82 Hangar 13 door (tower side) door stop weld is broken. needs to be re-enforced and re-welded.

In Progress

#81 Hangar 8-B back wall is extruding beyond the concrete pad because the angle iron frame is missing. Anchor new angle iron.

In Progress

#80 Hangar 12 bay 1 (John Walden) Thicker door stopper required. Weld in place. 1/4" flat bar should protrude an inch more.

In Progress

#79 Hangar 2-C door is sticking.

In Progress

#78 Hangar 1-B Door sticks and sheet metal is loose near the tracks.

In Progress

#77 Hangar 7 (AJ Jain) back wall is rusted and water seeps in during rain. Clean and seal the bottom of the sheet metal wall.

In Progress

#76 Hangar 14-A Pigeons have returned. Ensure ends of doors are closed off to prevent pigeon entry. Inspect hangar for signs of entry and install material to prevent re-entry and roosting.

In Progress

#75 Hangar 2C roof is leaking

In Progress

#74 Hangar 14E roof is leaking.

In Progress

#73 Hangar 14D Roof is leaking

In Progress

#72 Hangar 4B no Light is working

Work Complete